

 JOHNSON	Service Guide: Drive Motor MCB Supplement Sheet	
	Prepared by: Emilie McWilliams	Date Prepared: 2/27/2018

DESCRIPTION

When you are troubleshooting or replacing the drive motor or motor control board (MCB) on the treadmill, also complete the step below.

REQUIRED TOOLS

Pliers

SOLUTION

Make sure that the drive motor wire connectors fit securely on the posts on the MCB. If they are loose, crimp the connectors using pliers (shown below), and then reconnect them to the MCB.

